HISTORIC SITE SUMMARY SHEET

SURVEY NUMBER: HA-1719

BUILDING NAME: John A. Roach House

LOCATION: Putr

Putnam, Harford County, MD

BUILDING DATE: ca. 1910

DESCRIPTION: The John A. Roach House is a moderately sized, side-gable frame dwelling that grew by accretion over a number of decades. It is an undistinguished example of a not-uncommon architectural form for the dwellings of the middle and working class people in the early decades of the twentieth century. Neither the house nor the setting has integrity, as the dwelling lacks a substantial amount of interior original finishing materials and has had all of the windows replaced. Furthermore, the setting has been diminished by the construction of large concrete block buildings adjacent to the house. The blacksmith shop that was located on the property and operated by John Roach has not been extant for many decades.

SIGNIFICANCE: The John Roach House, highly modified throughout the last decades since its construction in 1910, has, in its present state, little historical association with the past, and minimal architectural interest. With the loss of the blacksmith shop and all outbuildings except the small corncrib, it has little association with the early twentieth century era of Harford County when blacksmith shops were an important part of the infrastructure and a common feature in the landscape in rural areas where draft horses were still widely utilized, primarily for agriculture.

Maryland Historical Trust State Historic Sites Inventory Form MARYLAND INVENTORY OF THE STORIC PROPERTIES

MARYLAND INVENTORY OF

Magi	No.	
DOE	ves	nc

1. Nam	(indicate pre	ferred name)		
historic	John Roach House		4.35	
and/or common	-			
2. Loca	ation			
street & number	2803 Charles St.		N/A	not for publication
Putna city, town(near	m upper crossroads)	x vicinity of	congressional district	4th
MD state		county	Harford	
	sification			
Category district building(s) structure site object	Ownership public both Public Acquisition in process being considered not applicable	StatusK_ occupied unoccupied work in progress AccessibleK_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Proper	ty (give names a	nd mailing addresse	s of <u>all</u> owners)
name Mr. &	Mrs. James Montgome	ry		
street & number	2803 Charles St.		telephone n	o.:
city, town Fal	lston	state	and zip code MD 21	047
5. Loca	ation of Lega	al Descripti	on	
courthouse, regi	istry of deeds, etc. Harfor	d County Courthous	e	liber 1928
street & number				folio 57
city, town Be1	Air		state	MD
6. Rep	resentation	in Existing	Historical Surv	eys
title N/A				
date			federal sta	te county loca
pository for s	urvey records			
city, town			state	

7. Desc	escription Survey No. HA-17			Survey No. HA-1719
Condition excellent good fair	deteriorated ruins unexposed	Check one unaltered altered	Check one original site moved date of mo	ve
				_

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

See continuation Sheet 7.1

8. Sign	nificance		Survey No. HA-171	.9
1500–1599 1600–1699 1700–1799	archeology-historic X agriculture architecture	community planning conservation	literature mllitary music t phllosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific date	s 1910	Builder/Architect Unkr	iown	· · · · · · · · · · · · · · · · · · ·
Арр	licable Criteria:A and/or licable Exception: el of Significance:	A _B _C _D		
Prepare bot support.	h a summary paragraph	of significance and	a general statement o	f history and

See Continuation Sheet 8.1

9. Major Bibliographical References

10.	Geographi	cal Data			
Acreage o Quadrang UTM Refer	of inventorial property	9.07 acres 11e plete UTM refer	cences	Quadrang	lle scale 1:24,000
AZone		rthing	B Zone	Easting	Northing
C E G			D F H		
	oundary description a		lapping state or co	ounty boundaries	
 List all st			lapping state or co	ounty boundaries	code
List all st		or properties over		ounty boundaries	
List all st state state		code	county	ounty boundaries	code
List all st state state	tates and counties fo	code code	county	ounty boundaries	code
List all st state state 11.	Form Preparents Markets Markets Amounties for the Suffness and counties for the Suffness and Cou	code code	county county al Historian	ounty boundaries	code
List all st state state	Form Preparents on MD SHA	code code code ared By s, Architectur	county county al Historian da		code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST
DHCP/DHCD
100 COMMUNITY PLACE
CROWNSVILLE, MD 21032-2023
514-7600

CONTINUATION SHEET 7.1 DESCRIPTION

Contributing Resources: 2

Non-contributing Resources: 4

DESCRIPTION SUMMARY

The John Roach House is located at the junction of Baldwin Mill Road (MD 165) and Charles Street in rural Harford County, near the west fork of Winters Run where it crosses MD 165. This area is located between Upper Crossroads and Putnam. There are six structures on the property, with only two pre-dating the final quarter of the twentieth century—the heavily altered, ca. 1910, frame dwelling and a frame corncrib. The remaining four structures are a concrete block barns or storage facilities, and a small modern frame shed. The John Roach House is a small frame dwelling, though heavily modified, which is typical for the early decades of the twentieth century. The corncrib likely dates to the same time as the house.

DESCRIPTION

The John Roach House is located north of Upper Crossroads in rural Harford County. The dwelling is a modestly sized structure located on a nine-acre remnant of portions of large land grants known as Salisbury, Improvement and Ogg, King of Basham. These were, for the most part, included in the 190 acres purchased by Tudor Chocke (Chorke, Chalk) in 1813 for 5 shillings, including the additional parcels of Weatherill's Last Addition, Bells Luck and Robert's Enlargement. It is probable that the Roach property, along with the Robert Amos House, (HA-1718) on the other side of the West Branch of Winters Run, were on a portion of Salisbury, immediately adjacent to Ogg, King of Basham, small parts of which were purchased by William Amos in 1879 (Land Record BBN1, F192) for 5 pounds, and Corbin Amos in 1836 for \$55.

The six structures located on the property are aligned in a row along the north side of Charles Street. The dwelling (1) is located to the east, closest to MD 165, with the shed, three concrete block structures, then a small frame corncrib on the far west. The two contributing resources on the property are the dwelling and one corncrib (6), likely dating to the early decades of the twentieth century. The dwelling likely replaced one attributed to Mrs. M. Chalk on the 1878 Martenet's map. There was another dwelling likely located adjacent to the property, well to the west along Charles Street. Though probably not included in the sale to Roach, he nonetheless may have occupied it as a tenant while he operated his blacksmith shop before building the existing small house. The current structure and the corncrib were likely constructed by Roach within fifteen years of his purchase of the property in 1897 (Land Record 92/315). That the same nine acres had sold eleven years earlier for triple the amount that Roach purchased it for leads to the conclusion that the Chalk house had been destroyed by the time Roach bought it. Roach operated a blacksmith shop, around the corner from the house, on MD 165, immediately adjacent to the roadway, during his tenure on the property from 1897 to 1937. Long time residents Mr. and Mrs. Jacob Aquilla Green report that they remember visiting the shop in the 1920's and 1930's.

The frame structure is clad with asbestos shingles, has a composite shingle roof, and is built into a slight incline, ascending the rise on the north. It is oriented to the south, facing the West Branch of Winters Run. The side-gable roof is extended to the rear to shelter a two-room outshut, and a cross gable surmounts the centered entrance on the south, or entrance, facade. There are cornerboards at the southeast and southwest corners. The dwelling assumed its present form as the result of construction occurring over many decades. Because of the radical renovation of the structure and lack of access it was not possible to visually inspect the interior of

CONTINUATION SHEET 7.2 DESCRIPTION

the structure or all of the exterior. Although it has been heavily altered, with a substantial loss of original finishing materials, and the windows have all been replaced with vinyl sash, the owner reports that during the renovation there was evidence that confirmed the building sequence; a small, two-over-two room dwelling, from the first decade of the twentieth century, that was expanded to the rear and to the west later in the century.

The original house was a two-room, one and one-half story, side-gable dwelling with chimneys, accommodating wood stoves, centered in the two end walls. Only one chimney is extant—located on the outside of the west end wall. This core is supported on a fieldstone foundation. During the period of the Edwards ownership (in the 1940's and 1950's) the structure was extended to the north will a full-width, two room, shed-roofed addition, supported on a concrete slab. A full width porch extended across the south entrance façade, supported on concrete block corner plinths. The porch is reached by means of five wood steps. Because it is built into a slight rise on the rear (north), the south facade is above-grade with a portion of the basement exposed in those sections under the porch where it is not obscured by a lattice wood skirt.

The south entrance façade is three bays in width, with two sash windows (one-over-one lights) on either side of the centered doorway, surmounted by very small windows at the second level, the tops of which abut the cornice bed mold of the overhanging soffit. The window in the center over the doorway, on the other hand, is identical to those in the first floor, extending almost the full height of the cross gable. The full width porch has been screened above a short wall clad by vertical wood siding.

The east elevation, composed of the east face of the original structure and of the rear extension, is punctuated by four openings---a window at the attic level centered in the gable end, a very small window below it in the main part, and a doorway and a window in the rear extension. The fenestration of the west side is much more regular, with one-over-one lights at the first level of either side of the brick chimney with smaller versions just above them. This elevation is the location of a kitchen wing, extending the rear wing to the west. This kitchen addition has a shallow side-gable roof, with a window in the west elevation and an entrance in the south face.

On a rise to the west of the dwelling is a small, recently installed shed (2), gable-roofed with a hopper window in the south elevation and entrance in the west-facing gable end. The three large, rectangle-shaped concrete block buildings are located between the shed (and house) on the east and the corncrib on the far east end of the array of buildings. The first (3) is a large garage, constructed of block and vinyl-sided frame, with two large garage bays opening on the south-facing gable end. The gambrel-roofed barn-like structure (4) also has the gable end oriented to south and Charles Street. The roof is clad with standing seam metal, and an entrance is located in the south bay of the long, east side wall. The next structure (5) to the west is almost identical, but has its long side to the roadway rather than the gable end. A hay door is at the second level in the east-facing gable end above large barn doors.

A very small (6) corncrib is located at the west end of this line of buildings. The side-gable structure has its long dimension parallel to Charles Street on the south, with an entrance in the east gable end.

DESCRIPTION CONTINUATION SHEET 7.3

CHAIN OF TITLE

Ann Montgomery	to \$125,00	James Montgomery and wife 125,000			2/25/1993 1928/57
Wlm. Durding and wife	to	Earl and Ann Montgomery			6/3/1977 1032/305
Wayne Edwards and wife	to	Wlm. D	urding		6/8/1963 607/447
2 Lots 1) Virgi	nia Coe		Wayne Edwards iry, 9 acres	12/1/1 337/2	949 8
2) Elva	Bachma and hu daught	sband	Wayne Edwards 30.9 acres nn A. Roach	7/30/1 278/3	1943 75
John A. Roach died 11/27/37	to Elva Ba	achman,	Elva Bachman , Administrator		Will Record File 10,462 AJG23/420
Ella Harrison and husband	to \$300	John A	. Roach		12/4/1897 92/315
Georgina Chalk (Biles)	to \$900	Ella Ha 9 acres			12/16/1886 56/139
George Chalk and wife, et. al Heirs of Masor	to n Chalk (•	iana Chalk ne resides)		2/16/1878 36/348
Isaac Stansburg	to	Masor	n Chalk eorge Chalk		5/29/1841 25/65

STATEMENT OF SIGNIFICANCE CONTINUATION SHEET 8.1

SGNIFICANCE SUMMARY

The John Roach House, highly modified throughout the last decades since its construction in 1910, has, in its present state, little historical association with the past, and minimal architectural interest. With the loss of the blacksmith shop and all outbuildings except the small corncrib, it has little association with the early twentieth century era of Harford County when blacksmith shops were an important part of the infrastructure and a common feature in the landscape in rural areas where draft horses were still widely utilized, primarily for agriculture.

STATEMENT OF SIGNIFICANCE

The John A. Roach House has been analyzed as an adjunct to the blacksmith operation, operated by its owner early in the twentieth century, and generally within the context of the Industrial/Urban Dominance Period (1870-1930), and the Modern Era (1930-Present) within Harford County. It has also been analyzed for its architecture. The area in which the site is located is known as Putnam, which is west of Bel Air, the county seat of Harford County. This area, like other areas in the hinterland of Bel Air, was settled in the 18th century. Harford County was officially established in 1773, by which time the center of population had shifted to the interior, thus occasioning the moving of the county seat to Bel Air by 1782 where a courthouse and jail were constructed by 1791

Commercial and industrial growth in Harford County began in the 18th century. The establishment of early industries was aided by the abundance of natural resources and exploitable waterpower along the Fall Line. By 1730, soil exhaustion had initiated the gradual replacement of tobacco by wheat cultivation, encouraging the milling industry. A gristmill, a sawmill and tannery were in operation along Bynums Run before 1773. Further commercial and industrial growth characterized the *Agricultural-Industrial Transition Period* (1815 to 1870). Development of the lumber industry led to the establishment of sawmills on most of the county's steams in the early nineteenth century. The establishment of a mill operated by Robert Amos (see HA-1718) on an adjacent may have established the crossroads as the location of services for the local population, optimum for the establishment of a blacksmith shop by John Roach.

The economy of Baltimore dominated the region during the *Industrial/Urban Dominance Period* (1870-1930), retarding additional large-scale industrial development in the county. Although new industries were established, including flint mining and vegetable canning, industrialization in urban areas far outpaced Harford County's development. During the *Modern Period* (1930-Present) Harford County underwent rapid development as population in the Baltimore region has increased and agricultural land is today being rapidly replaced by suburban housing development.

STATEMENT OF SIGNIFICANCE CONTINUATION SHEET 8.2

The John Roach House has been analyzed under applicable criteria of the National Register of Historic Places. It does not meet the requirements of Criterion A (association with a significant event); Criterion B (association with a significant person); and Criterion C (the work of a master or architectural merit). It has no known significance association with an historical event, an historical person, and is an undistinguished example of a small house type, thus it would not meet the requirements of Criterion C. Without archeological investigations it is uncertain whether there is any information potential, but given its late construction date it is unlikely that it would meet the requirements of Criterion D for any resources possibly located within the limits of construction impact for the bridge replacement project.

MARYLAND HISTORICAL TRUST REVIEW Eligibility recommended Eligibility not recommended Criteria: A B C D E F G None
Comments:
Reviewer, Office of Preservation Services Date
Reviewer, NR Program 8 23 00

رشر

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

GEOGRAPHIC ORGANIZATION: Piedmont

CHRONOLOGICAL/DEVELOPMENTAL PERIOD (s):

Industrial-Urban Dominance, 1870-1930

Modern - 1930 to Present

PREHISTORIC/HISTORIC PERIOD THEME (s): Architecture

RESOURCE TYPE

CATEGORY:

Buildings

HISTORIC ENVIRONMENT:

Rural

HISTORIC FUNCTION AND USE: Domestic/Single Dwelling/Residence

Domestic/Outbuilding/Corncrib

Subsistence/Agricultural Outbuildings/Barns (Non-C) Subsistence/Agricultural Outbuildings/Shed (Non-C)

KNOWN DESIGN SOURCE:

None

HA-1719 JOHN H. ROACH HOUSE PUTNAM, MARYLAND

BIBLIOGRAPHY CONTINUATION SHEET 9.1

Griffith, Dennis. Map of Harford County (1794).

Harford County Court Records-Land Records Office and Registrar of Wills.

Jennings, S. and L. W. Herrick. A Map of Harford County, Maryland (1858).

Martenet, Simon J. Martenet's Map of Harford County, Maryland (Baltimore, MD: Schnidt and Troe, 1878).


Suffness, Rita M. Personal Communication with Mr. and Mr. Jacob Aquilla Green (11-19-1999), Mr. and Mrs. Howard Popp, Jr. (8-10-1999), Mrs. Julie Montgomery (8-10-1999), and research staff of the Harford County Historical Society (various dates).

Weeks, Christopher. An Architectural History of Harford County, MD (Baltimore, MD: Johns Hopkins University Press, 1996).

Wright, Milton C. Our Harford Heritage: A History of Harford County (C. Milton Wright, 1967).









HA-1719 John A Roach House Putnam, Harford County R Suffres 811.155 negs at mostice Bldg1 Dwelling Su Corner 1/5



HA 1719 John A Roach House Putnam, Harford Chy in D R Suffrem 8110195 Belge 1 mg sAPU Dwelling SEComer



HA 1719 John A Roach House Putnam, Harford County 2 Softre 8-10-59 negs at MDSHPU Buldings 3, 4, 5, 6 Concrete Block and Looking west
3/5



HA 1719 John A Roach Harene Putnam, Harford Ch R Suffren 8-16.99 mosHPD Dwelling Sowon (principle) el evation



HA 1719 John A Roach House Vutnam, Harford Cy 12 Suffren 8-10.99 hegs at mb SHPL Frame shed South Glevatur 5/5